Preliminary damage survey report on 2015 Nepal Gorkha Earthquake

Pokhrel R.M., Chiaro G., Kiyota T., Katagiri T.

Institute of Industrial Science, University of Tokyo, Japan

Goda K.

Bristol University, UK

Sharma K.

Alberta University, Canada



Advance Party of Japanese Investigation Team for the 2015 Nepal Earthquake Disaster

JSCE: Japanese Society of Civil Engineers JGS: Japanese Geotechnical Society

ATC3, ISSMGE: Asian Technical Committee, Int. Society of Soil Mech. & Geotech. Eng.





PART I

Damage survey in Kathmandu City

Dr Pokhrel Rama Mohan (PhD)

JSPS Research Fellow Institute of Industrial Science University of Tokyo

1. Introduction



1.1. Geology of Kathmandu valley and surroundings



1.2. Geology of Kathmandu Valley



Schematic geologic cross-section of the Kathmandu basin sediments during the late Pleistocene (Sakai et al., 2002)

1.3. Morphology of Kathmandu Valley

Kathmandu valley is an intermountain basin (600 sq km) filled by lacustrine deposits derived from the surrounding mountains

The elevation of the Kathmandu valley varies from 1270m to 1400m



2. Kathmandu city



۲

•

2.1. Heritage buildings collapse (location A)



Basantapur Tower









Most of the temples are more than 500 years old



2.2 City center









2.3. Building collapse (North-west of Kathmandu)



Study area (location E)



At least 28 buildings totally collapsed or should be demolished Most heavily damaged buildings are located on the *alluvial soil deposit*

Along the Ring Road (location F)

Local ground motion amplification and/or loss of bearing capacity, poor quality of non-engineered RC buildings









2.4. Damage along Araniko Highway (location B)



Embankment settlement

Before earthquake



Extension completed in 2011

During survey





Photo source: wordpress.com

Southern side

Northern side



Section A-A'



Retaining walls cracks











• Damage due to poor compaction of the filling soil

Ground failure nearby embankment



Ground-failure-induced tilting and subsidence of buildings









2.5. Soil liquefaction (location C)



- No damage induced to surrounding buildings
- Water table very low during dry season

2.6. Road failure (location D)





PART II

Damage survey near Epicenter Area and Pokhara

Dr Chiaro Gabriele (PhD)

JSPS Research Fellow Institute of Industrial Science University of Tokyo

3. Trishuli & Melamchi



On the way to Trishuli

Rock fall







Villages encountered:

- Ranipauwa
- Nipala
- Battar (Bidur)
- Gerkhu
- > 80% houses damaged







Damage to Trishuli earth dam



Upstream

Embankment



Soil liquefaction



Liquefaction-induced lateral spreading





On the way to Melamchi

- 90 km from Mw=7.8 (4/25)
- 40 km from Mw=6.7 (4/26)









Melamchi











Weathered rock



Boulder (hard rock)



Weathered limestone



Landslides



Landslide #1



Looking from the road down to the river

Landslide #2

5. Pokhara valley

Distance from epicenter:

- 71 km from Mw=7.8 (4/25)
- 86 km from Mw=6.6 (4/25)
- 205 km from Mw=6.7 (4/26)

Armala area - sinkhole

Muddy water was observed after the earthquake

No new sinkholes and no change in sinkholes size

6. Bridges

7. Summary

- Survey damage was conducted in Kathmandu city, Trishuli, Melamchi, Epicenter area and Pokhara city
- In Kathmandu city, most of structural damage was observed in the city center (heritage buildings and old masonry houses) and in the north-west area along the ring road (non-engineered RC building, loss of bearing capacity of soft soils)
- Ground failure induced the settlement of an embankment along the Araniko Highway, sinking and tilting of a number of RC buildings

- In Trishuli, liquefaction was observed. However, most significantly, cracks along the upstream side of the earth dam are of concern
- In Melamchi, damage to houses and landslides were widely observed (close to Mw=6.7 epicenter of 4/26)
- In the epicenter area, many villages were completely devastated and a number of landslides could be observed
- In Pokhara valley, only minor damage to houses were observed. In Armala area, no new sinkholes were formed
- No damage to bridges was observed during the survey

8. Concluding remarks

- House inspection should be done as early as possible
- Inspection of the landslide area is also important because damaged rocks as well as large cracks still remain on the slope. Survived slopes could have further damage (aftershocks/during rainy season)
- We couldn't reach the mountain area where a natural landslide dam is reported. Need helicopter or long trekking
- The damage to the roads and buildings in the Kathmandu valley would be linked with ground condition
- Damage distribution in the fault area corresponds well with the characteristics of the earthquake (i.e. heavy damage in the east area while no damage in east (and south) area from the epicenter

Thank you very much for your kind attention!

Acknowledgement

Pokhrel P. (Tribhuvan University, Nepal) Kato, Y. (NHK) Hirano, M. and Kaneko, J. (The Mainichi Newspapers)