

Meeting with ASCE/TCLEE survey team on the 2011 Great East Japan earthquake at JSCE on June 13, 2011

## Damage of wastewater utilities in the 2011 off the Pacific coast of Tohoku Earthquake


Gaku Shoji, Univ. of Tsukuba



### Damage of sewer pipes and manholes



## Damage due to seismic excitations and induced liquefaction - courtesy of Urayasu city




# Damage and early restoration of sewage pipes at Urayasu city

Benten

#### Tomioka

Emergency restoration

Imagawa



Physical damage of No.3 pump house due to tsunami wave loads at Minami Gamo treatment facility

 Structural failure modes by inundation depth of about 8m to 9m
 Deformation of 1m or more in out-of-plane at the RC wall



Physical damage in the No.3 pump house by 8m to 9m inundation from the ground level at Minami Gamo treatment facility
Physical and functional failure modes of mechanical systems

1st floor

2nd floor



## Summary

Damage induced by ground shakings and liquefaction
 Damage induced by tsunami wave loads

The framework on seismic and tsunami resistant management for wastewater utilities should be rebuilt. e.g. Special committee at MLIT (Chair: Prof. Hamada)