

Bridge one:

Varzaghan-Tabriz road.

3 Spans

Piers: Stone

Deck: Concrete beams freely sitting on seats

Severe damage to abutments, Sliding of deck.



East view



Damage to Abutment- West view



Sliding of the bridge- West View



Cracks appeared due to landslides 100m after the bridge