

TRANSDISCIPLINARY APPROACH OF RISK GOVERNANCE AND THE FREVENTION OF SEDIMENT DISASTERS AFTER A MEGA SARBSHAKE - AN EXAMPLE OF THE 0403 EARTHQUAKE AND THE AFTERMATE TYPHOON EVENTS IN 2024, EASTERN TAIWAN





Chen-Yu Chen, Hsiao-Yu Huang

Ting-Chi TSAO
Deputy Director





Disaster Prevention Technology Research Center Sinotech Engineering Consultants, Inc., Taiwan

### **OUTLINE**

### Introduction


0403 Earthquake and it's Impact

Sediment Disasters after Mega Earthquake

Risk Governance and Disaster Prevention with Transdisciplinary Approach

2024 Typhoon Events

Conclusions & Ongoing Challenges




# Introduction - Sediment Disaster in Taiwan




# **INTRODUCTION**

# Historical Earthquakes around Taiwan




## **INTRODUCTION**







# **Disaster Response**

# Red/Yellow Alert during Typhoon









# 0403 Earthquake and it's Impact




## **0403 Earthquake** (07:58 AM, Apr.3, 2024, M<sub>L</sub>=7.2)




# **0403 Earthquake** (Apr.3, 2024, M<sub>L</sub>=7.2)




# Earthquake Triggered Landslides and Aftermath




# Earthquake Triggered Landslides and Aftermath







(Source: Chi Po-lin Foundation)



Risk Governance and Disaster Prevention with Transdisciplinary Approach



# Challenges – new disaster type and MUCH BIGGER



# Challenges – new disaster type

# Residents

Where are the dangerous areas?

When should I evacuate?

Who is going to explain these to me?

Risk identification,
Hazard mapping

Update red warning,
Cell broadcast

Local information meeting


# Railway Co., Highway Bu.

Would my facilities be affected?

When should I shut off the railway/road?


How could I utilize these information?

## Challenges – time is limited




## **Transdisciplinary Approach**

- ✓ Approach to solve multi-sector/stakeholder problems
- ✓ Based on science and technology findings
- ✓ Collaboration from public, private and civil sectors



(Source: Matsuura and Razak (2019), Disaster Prevention and Management 28 (6): 817-830)



Non-Engineering


**Engineering-Method** 

# Risk Identification



# **Landslide Inventory with Satellite**

- ■1,942 new landslides (1,521 Ha) identified with satellite image up to May 31.
- Updated regularly and FREE Download on web.
- ■Notify Railway Co., Highway Bu., Forest Bu. and other agencies since Apr.



農業部農村發展及水土保持署 函 農業部農村發展及水土保持署 函 地址:54044南投市中興新村光華路6號 远址:54044南投市中原新针光草路6號 承辦人: 頭蜂絵 電話:049-2347544 雪油:049-2347544 電子信箱: jhan0801@mail. ardswc. gov. tw 電子信箱: jhan0801@mail, ardswc, gov, tw 受文者:如正副本行文單位 :如正副本行文單位 份文日期:中華民國113年4月25日 中華民國113年6月26日 **發文字號: 異係監字第1132667930號** 農保監字第1132668121號 解密條件或保密期限: 檢送0403花蓮地震衛星影像刺釋新生崩塌成果1份,如說 : 檢送113年0403花蓮地震暨0423餘震後土石流潛勢溪流新生 崩塌判釋資料1份,如說明,請查照。 一、113年4月3日花蓮縣鄰近海城發生芮氏規模7.2地震,造成震 度5強以上地區(如花蓮縣秀林鄉等)發生多處坡地崩塌。本 0403花蓮地震暨0423餘震衛星影像新生崩塌判釋報告本署業 署為地震災後新生崩塌調查,持續蒐集或購置最新衛星影像 以113年6月4日農保監字第1132668058號函提供參考(含新生 二、本署利用Sentinel-2衛星(空間解析10公尺)、Planet衛星(空 崩塌位於26條土石流潛勢溪流集水區統計),合先敘明。 間解析3.7公尺)及航空照片等影像,綜合判釋面積0.1公頃 因應113年0403花蓮地震影響,農業部另以113年6月13日農 崩塌。截至4月21日,已判釋1,391處,總面積為 授農保字第1132668086號公開更新113年全臺土石流潛勢溪 流資料;其中新增土石流潛勢溪流4條皆位於花蓮縣秀林鄉 (附件1)。 、另依本署0403花蓮地震暨0423餘震後土石流潛勢溪流新生崩 塌判釋資料 (附件2);其中,序號1至序號12地震後新生崩 塌情形較為嚴重,請優先作好防災整備,並加強清疏等工

旨揭地震災後影像及新生崩塌判釋成果,已公開於本署


BigGIS巨量空間資訊系統(https://gis, ardswc, gov, tw/map/) 模式分析/災害事件衛星影像判釋成果/災害事件清單,並提

供KML檔下載,俾方便各界加值應用



### Field Investigation to Determine Hazard Type


- Type A: Landslide falls within current DF; update risk level, reduce alert threshold.
- Type B: Landslide falls within torrent catchment; add as new DF.
- Type C: Landslide falls on slope; add as Sediment Sensitive Area.











Landslide Affected Area

0403 Landslide

Chongde Vil., Hualien County

Houses: 5

LS Area: 7.43 Ha

LS Slope: 45~60 degrees

LS History: 0403 EQ, 2024

Image Date: Apr. 2024

15 were mapped by May 1<sup>st</sup>
45 by May 30<sup>th</sup>

Hualien SL0002 Landslide Hazard Map



# Debris Flow Torrent Hazard Mapping

gis.ardswc.gov.tw

Debris Flow Information Update

√ 1,732 + 4 Debris flow torrents

✓ 4 newly added in EQ area in June


Adjust rainfall threshold

Publicity

✓ Public on line

(https://246.ardswc.gov.tw/)


- √ BigGIS(https://gis.ardswc.gov.tw)
- √ TGOS (https://www.tgos.tw)
- ✓ Open Data (https://data.gov.tw)



### Risk Communication



# **Broadcast through Media**









■ 2024-07-23 4:56 下午 記者田俊浩/報導

凱米颱風影響臺灣 農村水保署呼籲山區民眾加強戒備 鎖定秀林鄉為重點關注地

隨凱米颱風影響臺灣,農村水保署二十三日表示,花蓮縣處於0403大地震過後,致災風險增加,更需注意;已鎖定秀林鄉為重點關注 地,包含當地的和仁部落、三棧南溪上下游及鄰近部落,都是風險較高的地方,為此已先進行河道清疏,但是颱風天下大雨土砂量仍



花種孫撰,山區土石朝勤,無村水保養評估後緊急問降花種用,秀林鄉,苗安鄉及群漁鎮,南濱鄉等5鄉 鎮市的土石名譽戒基準值,並敢動海區影像監控。國為太魯閣控客中心新錦文博一帶河床。(貿和縣,記 考王孫義續)

因應0403大震後汛期農業部啟動先期治山防災整備

- 工商時報 陳碧芬





大,需嚴密監控,依據警戒資訊請地方政府執行疏散

# Risk Communication



## **Visit Local Government**

- ✓ Ask the chief to update the evacuation plan.
- ✓ Remind the chief to enhance disaster mitigation and propaganda after the quake.
- ✓ Explains to the residents about the sediment sensitive area risks after the quake and to cooperate when evacuate.









	1	2	3	4	5	6	7	8	9	10	11	12
Visit Date	4/22	4/22	4/23	4/26	4/23	4/29	4/29	5/7	5/27	5/28	6/6	6/6
Office Visited	Hualien Township	Agr. Dept, Hualien County	Xiulin Twp.	Jian Twp.		Shoufeng Twp.	Fuli Twp.	Hualien County Magistrate	Chongde Vil. Head	Jingmei Vil. Head	Yuemei Vil. Head	Fengxin, Nanping Vil. Head

### Risk Communication



# **Governance Platform Monthly**

#### Member



9th River Man. **Branch** 



Hualien Branch, **ARDSWC** 



Hualien Branch, **Forestry Agency** 



Hualien Irrigation 💦 Agency



Hualien County Gov.



**Taiwan** Water Co.







#### **Purpose**

✓ Hold monthly meeting to enhance cross agency mitigation.

#### Goal

✓ Information exchange, resource sharing in Hualien region.





# 7

## **Regional Joint Inspection**

- √ 6/24, 6/27, 7/8, 8/9, 8/29 held joint inspections with Railway Co.
- ✓ 5/3, 8/2, 8/12 held joint inspections with **Highway Bureau** along Route 9.
- ✓ 7/1, 7/31 held joint inspections with local **Township Gov**.
- √ 8/12 Ministry of Transportation held discussion meeting regarding the long term mitigation alone the heavily stricken corridor.
















# **Emergency Engineering Treatment (Hualien D**

Risk Treatment



- ✓ Pre-event dredging in bottleneck sector.
- ✓ Temporary sediment trapping device installed in late May.
- ✓ Community table top exercise, CCTV installation.
- Heavy machinery stand by during typhoon event.




經緯度 V 目前位置未取得坐標資訊 高程(m) 28.8











**2024 Typhoon Events** 




# **Typhoon Gaemi**

Rainfall 7/24~7/26

Accu. **550** mm

Accu. OOO IIIIII









7/24 17:00

Accu. 307.5 mm

Max. **86.5** mm/hr





**CCTV Recorded DF Event** 

# **Typhoon Gaemi**



### **Hualien DF173**

# **Typhoon Gaemi**

- ✓ 7/23 Typhoon Warning,7/23 18:30 Yellow Alert,
  - 7/24 18:30 Red Alert
- ✓ 7/24 15:00 residents evacuated.
- ✓ Heavy machinery stand by and cleaned after DF event.

Residents



**Pre-Evacuation** 

# **Typhoon Gaemi**

In the 4 newly added debris flow torrents in the EQ area, sediment disasters were recorded in 3 during Typhoon Gaemi.







(Source: ARDSWC)

# **Typhoon Gaemi**

- **28** Debris Flow Red Alert
- 77 Debris Flow Yellow Alert
- 2 Large Scale Landslide
  Yellow Alert
- 54 Cell Broadcasting
- **3,296** evacuated
- No fatalities!




# [土石流及大規模崩塌警戒]花蓮縣秀林鄉崇德村共5處(花縣DF173),1小時累積雨量已達13mm、3小時累積雨量已達132mm、24小時累積雨量已達274mm,請提高警覺,農業部關心您。[Warning]Rainfall reached the warning level. ARDSWC. TEL:0800\_246\_246

**Heavy Rainfall Warning** 

L		Township	Flow	Scale Landslide	People Evacuated
	1	Xiulin	19	-	916
	2	Shoufeng	9	-	25
		Red Alert	28	0	
	3	Xiulin	13	-	187
	4	Shoufeng	11	1	79
	5	Jian	7	-	258
	6	Hualien City	3	-	20
Ī	7	Fenglin	9	-	83
	8	Guangfu	18	1	166
	9	Fonggbin	16	-	49
		Yellow Alert	77	2	

**Debris** 

Large



# Conclusions & Ongoing Challenges



### CONCLUSIONS



After mega earthquake new types and larger scale of sediment disaster became new challenges in eastern Taiwan.



An example of risk governance and management of sediment disaster in eastern Taiwan during 2024 typhoon season was given.



Applying transdisciplinary approach to tackle complex disaster type in future extreme climate scenario is necessary.

# **IGOING CHALLENGES**








### **ONGOING CHALLENGES**

Monitoring

馬太鞍溪堰塞湖變化





















Disaster Prevention Technology Research Center Sinotech Engineering Consultants, INC., Taiwan

tctsao@sinotech.org.tw

https://dptrc.sinotech.org.tw