


★砂川氾濫原の痕跡調査(岡山県)

- 調査日 : 平成30年7月24日
- 調査団員 : 吉田圭介:岡山大学、赤穂良輔:岡山大学
- 調査補助員 : 岡山大学 修士課程学生2名、学部生1名

調査内容

- 氾濫域浸水調査
- 範囲：高梁川，成羽川流域
- 目的：氾濫域における浸水深を計測し，どの高さまで氾濫水が来たか調査する.

調査内容(浸水深)



番号	水深[m]	水位[m]
1	0.8	5.20
2	1.2	5.52
3	2.2	5.41
4	0.8	5.50
5	0.9	5.60
6	0.3	4.80
7	0.8	5.11
8	0.7	5.17
9	0.8	5.12
10	0.7	5.78
11	0.9	5.04
12	0.9	8.62
13	1.2	5.28
14	0.9	5.31
15	1.8	5.59
16	1.3	4.81
17	1.5	4.98
18	1.6	6.28

1



1



1



1



2



2



2



3



3



3



3



4



4



4



5



5



5



5



6



6



6



7



7



7



8



8



8





9



9



9



9



10



10



10



11



11



11



11



12



12



12



13



13



13



13



14



14



14



14



15



15



15



16



16



16



16





17



17





18



18



18

