

## CONTENTS

1. **(Invited Paper)** Study on the Monitoring Technology for Slope Failure Using Optical Fiber Sensor . . . . . 1  
Shunji Kato, Hidetoshi Kohashi and Atsushi Huruya
2. A Bibliographic Review of Debris-Flow Monitoring Devices and Methods . . . . . 7  
Yasumasa Itakura, Hiroyuki Inaba and Toyoaki Sawada
3. Detecting and Warning Systems on Debris Flow by Monitoring Ground Tremor . . . . . 13  
Makoto Hikida, Toshiyuki Moriyama, Kazuyoshi Aida and Kouichi Ishitsuka
4. Study on Debris Flow Detection Vibration Sensor System Using Fourier Spectrum  
and Envelop-Analysis . . . . . 17  
Tsuneo Ohsumi, Takahiko Nagayama and Tomohiro Makinou
5. Approach of Earth Failure Prediction . . . . . 23  
Hideharu Saitoh, Shuichi Mori, Masami Ichikawa and Rie Iwamoto
6. Slope Disasters Monitoring Case of Ryu-ga-mizu Area of the Aira Caldera Wall, Kagoshima Prefecture . . . . . 29  
Satoru Kusunoki, Hiroshi Ikebe, Yukihiko Sakatani and Takashi Harada
7. An Internet Based Alarm System for Mitigating Rainstorm-Induced Landslides . . . . . 35  
Lin Wang and Rolando Orense
8. **(Invited Paper)** Critical Rainfall and Information . . . . . 41  
Muneo Hirano and Toshiyuki Moriyama
9. Uncertainties of Rain Observation and Soil Water Index . . . . . 47  
Kenji Okada
10. Research on Disaster Prediction System for Slope Failures Due to Rainfall . . . . . 53  
Kazunari Sako, Ryosuke Kitamura and Ryoichi Fukagawa
11. A Study on Employment of Critical Line by Using Prediction of Rainfall . . . . . 59  
Shigeki Kanda, Hiroyuki Ohishi, Hiroaki Takemoto and Kohei Furukawa
12. Warning and Evacuation System for the Sediment-Related Disaster . . . . . 65  
Shigeru Ogawa, Shuichi Ikebuchi and Hiroshi Gohda
13. Expression Examples of Observed Precipitation Data for People's Active Behavior of Disaster Prevention . . . . . 69  
Masahiro Kaibori, Shimpei Inoue and Masaru Nishimura
14. Research on Slope Failures Induced by Flood in August 2003 in Nukabira River Basin and its Causes . . . . . 75  
Yasuhiro Murakami, Makoto Nakatsugawa and Ken-ichi Takada
15. Geomorphological-Meteorological Characteristics of the Landslide Disaster 2003 in Northern Kyushu, and a  
Diagnosis of the Meteorological Condition . . . . . 81  
Tetsuya Kubota, Hiroshi Omura and Prem P. Paudel
16. Runoff Analysis of the Debris Flows in the Umi River Basin on July 19, 2003 . . . . . 87  
Hiroki Takaoka, Haruyuki Hashimoto, Kichan Park and Tetsuro Esaki

17. Geomorphologic and Geologic Characteristics of Landslides and Debris Flows Induced by 2003 Heavy Rainfalls, at Drainage Basin of Hara River, Dazaifu City	93
Takahito Kuroki, Nozomi Iso and Kensuke Goto	
18. Recurrence Interval of Debris Flows at Atsumari River, Minamata City, Inferred from Stratigraphy of Fan Deposits	99
Ryusuke Imura	
19. Peak Discharge of the Debris Flow in Minamata City on July 20, 2003	103
Hiroki Takaoka, Haruyuki Hashimoto, Kichan Park, Shinya Ikematsu, Shoichiro Kido and Makoto Hikita	
20. Study on Behaviors of Administration and Residents at Disaster of Minamata in July 2003	109
Kazuo Takahashi, Yuji Kawano and Shozo Nakamura	
21. A Field Study on Emergency Responses of Public Authorities against the July 2003 Debris Flow Disaster in Minamata, Kumamoto	115
Yasunori Hada, Shingo Nagamatsu and Kunihiro Fukudome	
22. A Field Study on the Evacuation Behavior of Residents on July 2003 Debris Flow Disaster in Minamata, Kumamoto	121
Kunihiro Fukudome and Shingo Nagamatsu, Yasunori Hada	
23. (Special Paper) Measures for Mitigation against Sediment-Related Disasters in Kagoshima Prefecture From the View of Warning and Evacuation	127
Yukihiko SAKATANI and Shizutoshi MAEDA	
24. Hydrogeomorphological Characteristics of a Deep-seated Landslide in the Harihara River Basin, Izumi City, Kagoshima Prefecture	133
Jitousono Takashi, Shimokawa Etsuro and Yuki Yoshi Teramoto	
25. The Urban Debris Flow Disaster in Shimabara City on August 20, 1993	139
Kichan Park, Haruyuki Hashimoto, Hiroki Takaoka and Kazuhiko Yamasaki	
26. Post-Eruption Water and Sediment Discharge in the Miyakejima Volcano	145
Yasuhiro Doi, Takao Yamakoshi, Katsuo Sasahara and Haruo Nishimoto	
27. A Case Study of the Landslide Generating in the Opposite Dip Structure	151
Shigeo Yamamoto, Kimimasa Kuroki and Hiroshi Yamaguchi	
28. Detection of Landslide Hazardous Slopes by Using Tree Deformation	155
Kazuro Mita	
29. A Consideration on Fluctuation of Probability of Slope Failure	161
Kohei Araki, Koki Ishino and Ryosuke Kitamura	
30. Slope Stability Analysis Considering Seepage Property of Slope	165
Satoru Ohtsuka, Ryo Yamashita and Hirofumi Ikemoto	